

MESSRS.
DUIM LTD
36, VASHUTINSKOE SH., KHMKI
141400 MOSCOW REGION
RUSSIA

Lumezzane, 24th July 2018

TO WHOM IT MAY CONCERN

We hereby inform you that from the year 2015 the manifold art. 850 has not been changed constructively. The wall thickness of the manifold is between 3,50 and 3,75 mm.

Yours faithfully,

ITAP S.P.A.
Agostino Patti
General Manager

ITAP S.P.A.
ITALY
AGOSTINO PATTI
PRESIDENT

для предъявления по месту требования

Настоящим уведомляем, что с 2015г. Серия коллекторов 850 конструктивно не изменялась. Толщина стенки коллектора составляет от 3,5 до 3,75 мм

Искренне Ваш,

ITAP S.P.A.
Президент компании
Августино Патти

ITAP S.P.A.
ITALY
AGOSTINO PATTI
PRESIDENT

